

**ecology and environment, inc.**

111 WEST JACKSON BLVD., CHICAGO, ILLINOIS 60604, TEL. 312-663-9415

International Specialists in the Environment

EPA Region 5 Records Ctr.



309380

March 26, 1986

Mr. Richard Utt
Supt. of Gov't Services
P.O. Box 2339
Glen Ellyn, IL 60138

Dear Mr. Utt:

I am requesting information about any changing conditions at Mallard Lake Landfill. Specifically, I am interested in any change in leachate and/or gas generation on site.

According to information relayed in recent phone conversations, Mallard Lake Landfill presently maintains a Leachate Collection System on site. Also, cover of 6" is required at the end of each day, which is inspected and logged. Subsurface material is compacted to a permeability of 10^{-7} cm/sec. to a depth of 10 feet. If a material is encountered that cannot be compacted to 10^{-7} cm/sec. it is removed and replaced.

I appreciate your environmental conscientiousness about Mallard Lake Landfill. I will promptly review the information you forward to me and get back to you about a possible site visit. Thank you for your time and concern.

Sincerely,

Bridget A. Haugh

BAH:db